

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:

Company Joe Helfrich Environmental Scientist III

Inspection Report

Permit Number:	C0070011
Inspection Type:	PARTIAL
Inspection Date:	Thursday, February 24, 2005
Start Date/Time:	2/24/2005 9:30:00 AM
End Date/Time:	2/24/2005 2:00:00 PM
Last Inspection:	Tuesday, January 04, 2005

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny 44 no wind, 10" of snow at the mine office

InspectionID Report Number: 544

Accepted by: whedberg 3/8/2005

Permitee: **HIAWATHA COAL CO INC**Operator: **HIAWATHA COAL CO INC**

Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1202, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership Types of Operation	Mineral Ow	nership	Ivpes	Of (Operatio	ทร
--------------------------------------	------------	---------	-------	------	----------	----

		_	
12,177.	.00 Total Permitted	✓ Federal	✓ Underground
290.	.00 Total Disturbed	☐ State	☐ Surface
	Phase I	☐ County	☐ Loadout
	Phase II	✓ Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hiawatha Complex. Snow depths at the turn off to the King 6 portals prohibited access to that portion of the mine complex. Areas that could be accessed included the King 4 & 5 portals, the mine office and the #1 slurry pond. There were no off-site impacts nor compliance issues noted during this inspection.

Inspector's Signature

Date

Monday, February 28, 2005

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Thursday, February 24, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011
Inspection Type: PARTIAL

Inspection Date: Thursday, February 24, 2005

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no pending amendments. The DOGM permit was issued on March 14, 2002 and expires on March 14, 2007.

2. Signs and Markers

Signs with the required information were posted at points of access to the mine complex. There was approximately 10" of snow at the Town of Hiawatha.

18. Support Facilities, Utility Installations

The support facilities at the King 4 & 5 portals were inspected. The area was covered with approximately 18" of snow. The road to this site is plowed during the winter months to facilitate the logging operations above the King 4 & 5 portals.